

## **2018/2019 Annual Performance Report**

### **General Information**

**System Name: Pinetops WWTP**

**Owner: Town of Pinetops**

**ORC: Phil Webb**

**Permit Number: NC0020435**

### **-Description of Collection System & Treatment Process**

- + The Collection System consist of 8, 10, and 12 inch clay and truss pipe.
- + 2 pump/lift stations with generators
- + The Treatment Process consist of a manual bar screen, grit chamber, oxidation ditch, secondary clarifier, chlorine contact chamber, post aeration, aerobic digester, and 3 sludge drying beds

### **-Performance**

- + 1 Violation for August 2019 for Ammonia Nitrogen
- + Overall Performance of both systems has been very good during the 12 month period ending on June 30<sup>th</sup>, 2019

**I certify that this report is complete and accurate to the best of my knowledge.**

**Phil O. Webb, ORC**

**Pinetops WWTP**